Concrete Batching Plant HZS60-1Q1000 list

No.

Name

8-meter conveying pump

Cement silo

Cement silo

1

2

3

Specification and model

11KW

Electric dust removal

Electric dust removal

3

2

1

Num

		_000 complete the second control of the control of	//Laws	
	JS1000 planetary mixing host hydraulic door opening, electric oiling	Double horizontal shaft forced mixer	JS1000	1
		Transmission Motor	18.5KW	2
		Bearing		Several
ĩ		Reducer		2
#G		Hydraulic unloading system		1
		High strength lining plate		Several
	ZHENGYI	Activity seal		Several
	ZHENGTI	Blender cover		1
Ш	Main framework			
	Main frame and circular arc warehouse	Main framework structure	200 Channel steel	1
1		Mixing layer platform		1
		Ladder, platform, railing		1
		Circular arc warehouse		1
111	Aggregate transportation system			
	PLD1600 four bin batching machine (separately measured)	Storage Bin	4×5m³	4
		Weighing Hopper	4×1.7m³	4
		Sensor	ZHENGYI	16
		Drive system	11Kw	1
		Conveyor	B=650mm	1
		Rack		1
		Screw Take-up		1
		Carrying idler		Several
	ZHENGYI	Drive system	11Kw	1
		Nylon Conveyor Belt	B=650mm	1
1	Inclined Belt Conveyor	Rack		1
		Screw Take-up		1
		Carrying idler		Several
IV	Metering System	I	I	
14	The state of the s			
14		Weighing Hopper		1
1	Cement scale (cement weighing)	Weighing Hopper Sensor		1 3
1	Cement scale (cement weighing)	The state of the s		100
1	Cement scale (cement weighing)	Sensor	7 LIENOVI	100
1 2	Cement scale (cement weighing) ater scale (water measurement)	Sensor Pump unloading	ZHENGYL	100
1		Sensor Pump unloading Weighing Hopper	ZHENGYL	3 1 1
1		Sensor Pump unloading Weighing Hopper Sensor	ZHENGYI	3 1 1
1		Sensor Pump unloading Weighing Hopper Sensor Pump unloading	ZHENGYI	3 1 1 3
2	ater scale (water measurement)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper	ZHENGYI	3 1 1 3
2	ater scale (water measurement) dmixtures (Admixture Measurement)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor	ZHENGYI	3 1 1 3 1 1 3
2	ater scale (water measurement)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve	ZHENGYI	3 1 1 3 1 3
2	ater scale (water measurement) dmixtures (Admixture Measurement)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper	ZHENGYI	3 1 1 3 1 3
2	ater scale (water measurement) dmixtures (Admixture Measurement)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor	ZHENGYI	3 1 1 3 1 3 1 1 3
3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor	ZHENGYI 17 inch color monitor	3 1 1 3 1 3 1 1 3
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer	17 inch color monitor	3 1 1 3 1 3 1 1 3
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve		3 1 1 3 1 3 1 1 3
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer	17 inch color monitor Chinese and English	3 1 1 3 1 3 1 1 3
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer Printer	17 inch color monitor Chinese and English	3 1 1 3 1 1 3 1 1
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash) Control System	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer Printer Operate console	17 inch color monitor Chinese and English	3 1 1 3 1 1 3 1 1 1 1 1 1 1 1
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash)	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer Printer Operate console Power control cabinet	17 inch color monitor Chinese and English	3 1 1 3 1 1 3 1 1 1 1 1 1 1 1
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash) Control System	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer Printer Operate console Power control cabinet Air Circuit Breaker	17 inch color monitor Chinese and English	3 1 1 3 1 1 3 1 1 1 1 1 1 1 1 1 Several
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash) Control System	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer Printer Operate console Power control cabinet Air Circuit Breaker Contactor	17 inch color monitor Chinese and English	3 1 1 3 1 1 3 1 1 3 1 1 1 1 1 1 Several Several
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash) Control System	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer Printer Operate console Power control cabinet Air Circuit Breaker Contactor Relay	17 inch color monitor Chinese and English	3 1 1 3 1 1 3 1 1 3 1 1 1 1 3 1 1 1 Several Several Several
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash) Control System	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer Printer Operate console Power control cabinet Air Circuit Breaker Contactor Relay Weighing Module	17 inch color monitor Chinese and English	3 1 1 3 1 1 3 1 1 3 1 1 1 1 1 Several Several Several
1 2 3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash) Control System	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer Printer Operate console Power control cabinet Air Circuit Breaker Contactor Relay Weighing Module Button	17 inch color monitor Chinese and English	3 1 1 3 1 1 3 1 1 3 1 1 1 1 3 1 1 1 Several Several Several Several
3	ater scale (water measurement) dmixtures (Admixture Measurement) Fly ash scale (measurement of fly ash) Control System	Sensor Pump unloading Weighing Hopper Sensor Pump unloading Weighing Hopper Sensor Pneumatic Butterfly Valve Weighing Hopper Sensor Pneumatic Butterfly Valve Control Computer Printer Operate console Power control cabinet Air Circuit Breaker Contactor Relay Weighing Module Button Pilot Lamp	17 inch color monitor Chinese and English 24 needles	3 1 1 3 1 1 3 1 1 3 1 1 1 3 1 1 1 1 Several Several Several Several Several

LSY219-8M

50T Vertical

100T Vertical